


LYNX: MALE 50 PIN 'D'

**TASCAM: MALE 38 PIN ELCO
CONN B ("ACCESSORY")**



REV	DESCRIPTION
.001	R2 ADDED TO REC TALLY FOR PULLUP.
.00A	DWG# 30-0034-00A WAS FILE 40.002. PAIR COLORS, UNUSED PAIR INFO ADDED. LYNX PIN 12 ADDED.
9-21-88 AD	
5	REHEARSE CMD. ADDED TO PIN BB ON CONN. B
4/21/89 mc	
C	ADDED PLAY TALLY; CHANGED DWG. #: WAS 30-0034-00B
1/5/90 BT	
D	MODIFY SERVO RELAY CONNECTION TO ACCOMMODATE TASC ATR-80; CORRECT PLAY TALLY PIN DESIGNATION ON MACH. END OF CABLE.
5/13/90 BT	
E	CORRECT GROUND PIN ON CONN. B TO ACCOMMODATE ATR-80; ADD REV 'B' NOTES
6/20/90 BT	
REV F	CORRECTED TYPO, MAIN UNIT GND ON CONN 'B' WAS 'RR'. UPDATED TITLE BLOCK.
4/22/91 MS	

TEN PAIR CABLE UNUSED PAIR:
NONE

*= LYNX MODULES WITH U20 ONLY

CABLE APPLIES TO:
40-SERIES ATR-60 SERIES
MS-16

(C) 1991 TIMELINE, INC. 2401 Dogwood Way Vista CA 92083		APP'D <i>MC</i>
SCHEMATIC CABLE ASSEMBLY TASCAM TYPE A		CHK'D
CONFIDENTIAL	DATE	4/22/91
DWG	REV	PAGE
70D039-20	F	1
	SIZE	B