


# TEAC<sup>®</sup> AMERICA, INC.



## MOTOR REPLACEMENT:

- MODEL 122MKII - SHORT, BY SOLDER, THE CONNECTOR MARKED "4.8"
- MODEL 238 - SHORT, BY SOLDER, THE CONNECTOR MARKED "9.6"

## 4-5. TAPE SPEED

**CAUTION:** After replacement of the capstan motor assembly, be sure to short-circuit (by soldering) the points on the assembly shown by the arrow in Fig. 4-10. Otherwise, correct tape speed adjustments are not ensured.